

480 volt 12 lead motor wiring diagram

****Understanding the 480 Volt 12 Lead Motor Wiring Diagram: A Practical Guide****

480 volt 12 lead motor wiring diagram is a crucial reference for electricians, engineers, and maintenance professionals working with three-phase electric motors. These diagrams provide the roadmap to correctly connect the motor leads to the power supply, ensuring optimal performance, safety, and longevity of the motor. Whether you're dealing with a new installation or troubleshooting an existing motor, understanding how to interpret and apply a 12 lead motor wiring diagram at 480 volts can save time and prevent costly mistakes.

What Is a 480 Volt 12 Lead Motor?

Before diving into the wiring diagram itself, it's helpful to clarify what a 480 volt 12 lead motor is. This type of motor is a three-phase induction motor, commonly used in industrial settings, where robust power and versatility are required. The "12 lead" designation refers to the number of electrical connection points (leads) brought out from the motor's stator windings. These leads allow for different wiring configurations, enabling the motor to operate at various voltages and connections such as wye (star) or delta.

Why a 12 Lead Motor?

The 12-lead design provides flexibility. It allows a motor to be wired in multiple configurations:

- ****Dual voltage operation:**** For example, a motor can be wired for either 230 V or 460 V.
- ****Wye or delta connections:**** Each type affects the motor's performance characteristics, such as starting torque and current.
- ****Parallel or series winding connections:**** This impacts the voltage rating and current draw.

At 480 volts, the motor is typically wired in a delta configuration, but the 12 leads enable switching between configurations to suit the application.

Breaking Down the 480 Volt 12 Lead Motor Wiring Diagram

A 12 lead motor wiring diagram may look intimidating at first glance, but once you understand the basics, it becomes much easier to interpret.

Understanding the Motor Leads

The 12 leads are usually labeled U1, V1, W1, U2, V2, W2, U3, V3, W3, U4, V4, and W4. These represent the ends of the three coil sets inside the motor's stator. The goal of the wiring diagram is to show how these leads should be connected to form the proper winding configuration.

- **U1, V1, W1, U2, V2, W2:** These are the primary ends of the three phases.
- **U3, V3, W3, U4, V4, W4:** These are the secondary ends, which can be connected in series or parallel depending on the voltage and connection type.

Common Connection Types in 480V Motors

At 480 volts, the two most common connections are:

- **Delta Connection:** This connects the windings end-to-end forming a closed loop resembling a triangle. Each corner of the triangle is connected to a phase of the power supply. This configuration is suited for higher voltage operation like 480V and provides high starting torque.
- **Wye (Star) Connection:** This is more common for lower voltage applications and involves connecting one end of each winding together to form a neutral point. It's less common at 480V but sometimes used depending on the application.

The 12 lead configuration allows switching between these by changing the wiring connections as shown in the wiring diagram.

How to Read a 480 Volt 12 Lead Motor Wiring Diagram

Interpreting the wiring diagram involves understanding the schematic symbols and the layout of connections.

Identifying Lead Pairings

The motor windings are arranged in pairs that must be connected according to the diagram. For example, in a delta connection, you might connect U1 to W4, V1 to U4, and W1 to V4, forming the triangle. The remaining leads are then connected to the power supply phases.

Step-by-Step Wiring Process

1. ****Label each lead:**** Double-check the labels on each wire to avoid confusion.
2. ****Consult the wiring diagram:**** Identify the correct leads for the desired connection (delta or wye).
3. ****Make the connections:**** Use wire nuts or terminal blocks to join the leads as per the diagram.
4. ****Connect power supply leads:**** Attach the power lines to the motor terminals marked for the three phases.
5. ****Verify connections:**** Use a multimeter to check for continuity and correct phases before powering up.

This process ensures that the motor runs smoothly and avoids issues like phase imbalance or overheating.

Common Mistakes and Troubleshooting Tips

Working with 480 volt 12 lead motors requires attention to detail. Here are some common pitfalls and how to avoid them:

- ****Mixing up leads:**** Mislabeling or connecting the wrong leads can cause the motor to run in reverse or not start.
- ****Incorrect connection type:**** Wiring a motor intended for delta in wye configuration at 480 volts can cause damage.
- ****Loose connections:**** These can lead to arcing and motor failure.
- ****Overlooking voltage ratings:**** Always ensure the wiring matches the motor's voltage specifications.

To troubleshoot, check the wiring against the diagram, measure resistance between leads, and verify that the motor's phase rotation is correct once powered.

Applications and Benefits of Using a 480 Volt 12 Lead Motor

These motors are favored in industrial environments such as manufacturing plants, HVAC systems, and heavy machinery because of their versatility and power handling.

Benefits include:

- **Flexibility in voltage application:** The 12 lead setup allows configuring the motor for various voltage systems.
- **Improved motor life:** Correct wiring reduces electrical stress on the motor windings.
- **Efficient power usage:** Proper connection ensures optimal torque and current draw.
- **Ease of maintenance:** Having multiple leads accessible simplifies testing and troubleshooting.

Tools and Safety Considerations

When working with a 480 volt 12 lead motor wiring diagram and actual hardware, safety is paramount.

Essential tools:

- **Multimeter or megohmmeter:** To check continuity and insulation resistance.
- **Screwdrivers and wire strippers:** For secure connections.
- **Insulated gloves and safety glasses:** To protect against electrical hazards.

Safety tips:

- Always disconnect power before working on motor wiring.
- Follow lockout/tagout procedures.
- Double-check wiring diagrams and connections.
- Use the correct wire gauge and connectors rated for 480 volts.

Exploring a 480 volt 12 lead motor wiring diagram reveals just how versatile and adaptable these motors are. Proper understanding and application of the wiring diagram not only enhance the motor's performance but also contribute to safer and more efficient industrial operations. Whether you're an experienced electrician or a student learning about motor controls, familiarizing yourself with these wiring principles is an invaluable skill in the world of electric motors.

Frequently Asked Questions

What is a 480 volt 12 lead motor wiring diagram used for?

A 480 volt 12 lead motor wiring diagram is used to correctly connect and configure a three-phase motor that has 12 leads allowing different wiring configurations such as star (wye) or delta for operation at 480 volts.

How do you identify the leads in a 12 lead motor for 480 volt wiring?

In a 12 lead motor, the leads are usually numbered from T1 to T12. The wiring diagram specifies which leads to connect together to configure the motor for 480 volts, typically by grouping the windings in a delta configuration.

Can a 12 lead motor be wired for both 230V and 480V?

Yes, a 12 lead motor can be wired for both 230V and 480V by changing the wiring connections between the leads. For 230V, the motor is usually connected in a star (wye) configuration, while for 480V, a delta configuration is used.

What is the difference between star and delta wiring in a 480 volt 12 lead motor?

Star (wye) wiring connects one end of each winding together, creating a neutral point, which is suitable for lower voltage operation like 230V. Delta wiring connects the windings in a closed loop, suitable for higher voltage operation like 480V, providing full line voltage across each winding.

Are there standard color codes for the leads in a 12 lead 480V motor wiring diagram?

While color codes may vary by manufacturer, common practice is to number the leads from T1 to T12 rather than relying solely on color. It is essential to refer to the motor's wiring diagram and nameplate for accurate identification.

What safety precautions should be taken when wiring a 480 volt 12 lead motor?

Safety precautions include ensuring the power is disconnected before wiring, verifying voltage ratings, using appropriate personal protective equipment (PPE), following the wiring diagram precisely, and double-checking connections to avoid damage or injury.

Where can I find a reliable 480 volt 12 lead motor wiring diagram?

Reliable wiring diagrams can be found in the motor's user manual, on the motor nameplate, from the manufacturer's website, or in electrical code books and industry standards related to motor installation and wiring.

Additional Resources

480 Volt 12 Lead Motor Wiring Diagram: A Technical Exploration

480 volt 12 lead motor wiring diagram serves as a crucial reference for electrical engineers, electricians, and maintenance professionals working with three-phase motors. These diagrams provide the necessary information to correctly connect and configure 12 lead motors, commonly used in industrial settings where 480-volt power supplies are prevalent. Understanding the intricacies of these diagrams is essential for ensuring optimal motor performance, safety, and compliance with electrical standards.

The Fundamentals of 480 Volt 12 Lead Motor Wiring

At the core of the 480 volt 12 lead motor wiring diagram is the designation of twelve connection points or leads on the stator winding of the motor. This configuration allows for versatile wiring options, enabling multiple connection schemes such as series, parallel, and different voltage configurations. The 12 leads correspond to the three-phase windings, each divided into four sections, enabling various combinations to achieve different voltage and current ratings.

The 480-volt rating typically relates to the line-to-line voltage in industrial power systems in North America. Motors designed for this voltage must be wired precisely to handle the electrical load without overheating or inefficiency. The 12 lead configuration provides the flexibility to wire the motor for either 230/460 volts or 460/480 volts, depending on the application requirements.

Understanding the Lead Groupings and Numbering

Each of the twelve leads is numbered from 1 to 12, and these numbers correspond to specific winding terminals. The winding leads are grouped into three sets of four leads each, representing the three phases—usually designated as U, V, and W or T1 through T12. The standard numbering convention is as follows:

- Leads 1, 2, 3, and 4 - Phase U
- Leads 5, 6, 7, and 8 - Phase V
- Leads 9, 10, 11, and 12 - Phase W

Within each phase group, the leads are paired to form two coils. Properly connecting these coils in series or parallel affects the motor's voltage and current characteristics.

Wiring Configurations Enabled by the 12 Lead Design

The versatility of a 12 lead motor lies in its ability to be connected in multiple configurations to accommodate different voltage supplies or operational needs. The two primary configurations for 480-volt motors are the series and parallel connections, each offering distinct electrical and performance implications.

Series Connection

In a series connection, pairs of coils within each phase are connected end-to-end, effectively doubling the number of turns in the winding. This configuration is typically used for higher voltage applications, such as 460 to 480 volts. The motor windings are arranged so that the voltage rating per coil section aligns with the supply voltage, ensuring efficient current flow and torque output.

Series wiring generally results in lower current per coil but higher voltage across the winding, which matches the 480-volt supply. This connection is less prone to overheating but requires careful attention to the lead connections to prevent phase imbalances.

Parallel Connection

Conversely, the parallel connection pairs the coils side-by-side, halving the voltage across each coil but doubling the current capacity. This configuration is suitable for lower voltage supplies, such as 230 volts. The parallel wiring reduces the impedance of the motor windings, allowing for higher current flow at a lower applied voltage.

When wiring a 12 lead motor for 480 volts in parallel, the leads must be connected to ensure proper current distribution across the coils. Failure to do so can cause uneven heating and reduce motor lifespan.

Interpreting a 480 Volt 12 Lead Motor Wiring Diagram

A typical 480 volt 12 lead motor wiring diagram provides a schematic representation showing how the twelve leads are interconnected. These diagrams usually illustrate the three phases and the internal coil arrangements, along with external terminal connections.

Key elements to look for in these diagrams include:

- Lead numbering and grouping
- Coil pairs and their connections (series or parallel)
- Terminal block layout
- Connection points for external power supply
- Grounding and protective devices

Understanding these components within the wiring diagram enables technicians to correctly set up the motor for specific applications.

Common Symbols and Notations

Wiring diagrams often incorporate standardized electrical symbols to depict coils, terminals, and connections. For instance, coils may be shown as inductors with lead numbers annotated, while terminal points are marked with circles or squares containing the lead number.

Color codes or labels might also be included to identify phases or to

highlight connections for star (wye) or delta configurations. Recognizing these symbols is essential when translating the diagram into physical wiring tasks.

Application Considerations and Safety Aspects

Wiring a 12 lead motor for 480 volts demands meticulous attention to detail, not only for performance but also for safety. Incorrect wiring can lead to motor damage, excessive current draw, or hazardous conditions such as electrical shock or fire.

Voltage Compatibility and Motor Ratings

Before wiring, it is critical to verify the motor's voltage rating and ensure that the connection scheme matches the power supply. Motors rated for 460/480 volts often have nameplates indicating acceptable wiring configurations and maximum current ratings. Deviating from these specifications can cause premature motor failure.

Star (Wye) vs Delta Connections

Beyond series and parallel wiring, 12 lead motors can be configured in star (wye) or delta arrangements, each affecting the motor's operational characteristics.

- **Star (Wye) Connection:** Offers a neutral point and lower phase voltage, often used for starting motors or reducing inrush current.
- **Delta Connection:** Provides full line voltage across each winding, delivering maximum torque and power output.

Choosing between these configurations depends on the application requirements and the nature of the load.

Grounding and Protective Devices

Proper grounding of the motor frame and use of protective devices like circuit breakers and overload relays are indispensable in 480 volt systems. Wiring diagrams frequently indicate grounding points to ensure compliance with electrical codes and to enhance operator safety.

Comparing 12 Lead Motors to Other Lead Configurations

While 12 lead motors are highly versatile, they are not the only option available. Motors with 6 or 9 leads exist, each with specific wiring capabilities.

- **6 Lead Motors:** Simpler wiring, usually fixed for a single voltage rating, less flexible for multiple voltages or configurations.
- **9 Lead Motors:** Intermediate flexibility, often used in dual voltage applications but with fewer wiring options than 12 lead models.

The advantage of 12 lead motors lies in their adaptability, allowing a single motor to be wired for different voltages and connection types, which can reduce inventory costs and improve operational flexibility.

Challenges in Wiring 12 Lead Motors

Despite their advantages, 12 lead motors introduce complexity in installation. Technicians must carefully interpret wiring diagrams and verify connections with multimeters to avoid mistakes. Miswiring can cause phase imbalances, increased vibration, or inefficient motor performance.

Training and experience are critical for personnel handling these motors, and access to clear, manufacturer-provided wiring diagrams is essential.

Practical Tips for Working with 480 Volt 12 Lead Motor Wiring Diagrams

Successful wiring of 12 lead motors at 480 volts involves a methodical approach:

1. **Review the Manufacturer's Documentation:** Always start with the motor's nameplate data and wiring diagram provided by the manufacturer.
2. **Identify Lead Numbers and Groupings:** Use the diagram to understand which leads form coils and how they should be connected.
3. **Choose the Correct Connection Scheme:** Determine whether series or parallel wiring is appropriate based on the supply voltage and motor

rating.

4. **Use Proper Tools and Equipment:** Employ insulated tools, a reliable multimeter, and protective gear during wiring.
5. **Double-Check Connections:** Verify continuity and correct phase sequencing before energizing the motor.
6. **Follow Safety Protocols:** Ensure power is disconnected before wiring and use lockout/tagout procedures.

Adhering to these best practices reduces downtime and safeguards both equipment and personnel.

Implications for Industrial Automation and Maintenance

In industrial automation, 480 volt 12 lead motor wiring diagrams are indispensable for integrating motors into complex systems. Accurate wiring facilitates the use of variable frequency drives (VFDs), soft starters, and other motor control devices, enabling energy savings and enhanced process control.

From a maintenance perspective, having access to detailed wiring diagrams accelerates troubleshooting and repairs. Diagnosing wiring faults, phase imbalances, or insulation failures becomes more straightforward, minimizing production interruptions.

The growing emphasis on energy efficiency and reliability in industrial environments further highlights the importance of precise motor wiring, making the 12 lead configuration a preferred choice for many applications.

The technical depth and flexibility offered by the 480 volt 12 lead motor wiring diagram underscore its role as a foundational element in modern electrical motor applications. Its ability to accommodate various voltage levels and connection schemes makes it a valuable asset in optimizing motor performance while aligning with industry standards and safety requirements.

[480 Volt 12 Lead Motor Wiring Diagram](#)

Find other PDF articles:

<https://old.rga.ca/archive-th-029/pdf?trackid=JjC34-0510&title=ill-become-a-villainess-that-goes-down-in-history.pdf>

480 volt 12 lead motor wiring diagram: Electrical Motor Controls for Integrated Systems Gary Rockis, Glen A. Mazur, 2005 Electrical Motor Controls for Integrated Systems continues the long tradition of technical content presented in a user-friendly format. A comprehensive overview of the control industry is augmented with practical applications used in the field. With new, large detailed illustrations, contemporary photographs, and informative factoids, the premier motor control text remains the first choice of electrical training programs.

480 volt 12 lead motor wiring diagram: Direct Support and General Support Maintenance Manual , 1991

480 volt 12 lead motor wiring diagram: A Practical Approach to Motor Vehicle Engineering and Maintenance Allan Bonnick, Derek Newbold, 2011-05-26 Fully updated and in line with latest specifications, this textbook integrates vehicle maintenance procedures, making it the indispensable first classroom and workshop text for all students of motor vehicle engineering, apprentices and keen amateurs. Its clear, logical approach, excellent illustrations and step-by-step development of theory and practice make this an accessible text for students of all abilities. With this book, students have information that they can trust because it is written by an experienced practitioner and lecturer in this area. This book will provide not only the information required to understand automotive engines but also background information that allows readers to put this information into context. The book contains flowcharts, diagnostic case studies, detailed diagrams of how systems operate and overview descriptions of how systems work. All this on top of step-by-step instructions and quick reference tables. Readers won't get bored when working through this book with questions and answers that aid learning and revision included.

480 volt 12 lead motor wiring diagram: ,

480 volt 12 lead motor wiring diagram: Electrical World , 1910

480 volt 12 lead motor wiring diagram: Manuals Combined: U.S. Army M809 M110 M112 M113 6X6 5-Ton Diesel Truck Operator Repair Parts Manuals , Over 5,100 total pages
CONTENTS: Operator Manual - 414 pages - June 14, 1985 - w/Changes 1-4TM 9-2320-260-10TO
36A12-1C-481 Unit Repair Manual - 1339 pages - April 1, 1995TM 9-2320-260-20TO
36A12-1C-491 Depot Repair Manual Vol 1 - 653 pages - July 1, 1994TM 9-2320-260-34-1TO
36A12-1C-1122-1 Depot Repair Manual Vol 2 - 865 pages - June 1, 1994TM 9-2320-260-34-2TO
36A12-1C-1122-2 Parts List Vol 1 - 696 pages - September 1, 2003TM 9-2320-260-24P-1TO
36A12-1C-382-1 Parts List Vol 2 - 1020 pages - September 1, 2003TM 9-2320-260-24P-2TO
36A12-1C-382-2 Hand Receipt - 20 pages - January 31, 1979TM 9-2320-260-10-HRLubrication Order
- 35 pages - November 4, 1983TM 9-2320-260-12Transportability Guidance - 78 pages - July 17, 1986
- w/Change 1TM 55-2320-260-15-1 These manuals cover the following vehicles: M809 Series Trucks,
Diesel, 5-Ton, 6x6M810 Truck, Chassis (2320-00-051-0586 & 2320-00-051-0585)M812A1 Truck,
Chassis, Rocket Launcher (2320-00-050-9040)M813 Truck, Cargo (2320-00-050-8902 &
2320-00-050-8890)M813A1 Truck, Cargo (2320-00-050-8913 & 2320-00-050-8905)M814 Truck,
Cargo (2320-00-050-8988 & 2320-00-050-8987)M815 Truck, Bolster, Logging
(2320-00-050-8927)M816 Truck, Wrecker, Medium (2320-00-051-0489)M817 Truck, Dump
(2320-00-050-8970 & 2320-00-051-0589)M818 Truck, Tractor (2320-00-050-8984 &
2320-00-050-8978) M819 Truck, Tractor, Wrecker (2320-00-050-9004)M820 Truck, Van, Expansible
(2320-00-050-9006)M820A1 Truck, Van, Expansible (2320-00-050-9007)M820A2 Truck, Van,
Expansible (2320-00-050-9010)M821 Truck, Stake, Bridge Transporting
(2320-00-050-9015)NHC-250 Cummins 6 Cylinder Diesel Engine

480 volt 12 lead motor wiring diagram: Perpetual Trouble Shooter's Manual John Francis Rider, 1936

480 volt 12 lead motor wiring diagram: Perpetual Trouble Shooter's Manual John Francis Rider, 1940

480 volt 12 lead motor wiring diagram: Manuals Combined: U.S. Army M813 M813A1 M814 5 Ton Cargo Truck - Repair Operator Parts Tech Pubs , Over 5,100 total pages ...

CONTENTS: Operator Manual - 414 pages - June 14, 1985 - w/Changes 1-4 TM 9-2320-260-10 TO 36A12-1C-481 Depot Repair Manual Vol 1 - 653 pages - July 1, 1994 TM 9-2320-260-34-1 TO 36A12-1C-1122-1 Depot Repair Manual Vol 2 - 865 pages - June 1, 1994 TM 9-2320-260-34-2 TO 36A12-1C-1122-2 Unit Repair Manual - 1339 pages - April 1, 1995 TM 9-2320-260-20 TO 36A12-1C-491 Parts List Vol 1 - 696 pages - September 1, 2003 TM 9-2320-260-24P-1 TO 36A12-1C-382-1 Parts List Vol 2 - 1020 pages - September 1, 2003 TM 9-2320-260-24P-2 TO 36A12-1C-382-2 Transportability Guidance - 78 pages - July 17, 1986 - w/Change 1 TM 55-2320-260-15-1 Hand Receipt - 20 pages - January 31, 1979 TM 9-2320-260-10-HR Lubrication Order - 35 pages - November 4, 1983 TM 9-2320-260-12 The manuals cover the following U.S. Army vehicles: M812A1 Truck, Chassis, Rocket Launcher (2320-00-050-9040) M813 Truck, Cargo (2320-00-050-8902 & 2320-00-050-8890) M813A1 Truck, Cargo (2320-00-050-8913 & 2320-00-050-8905) M809 Series Trucks, Diesel, 5-Ton, 6x6 M810 Truck, Chassis (2320-00-051-0586 & 2320-00-051-0585) M814 Truck, Cargo (2320-00-050-8988 & 2320-00-050-8987) M815 Truck, Bolster, Logging (2320-00-050-8927) M816 Truck, Wrecker, Medium (2320-00-051-0489) M817 Truck, Dump (2320-00-050-8970 & 2320-00-051-0589) M818 Truck, Tractor (2320-00-050-8984 & 2320-00-050-8978) M819 Truck, Tractor, Wrecker (2320-00-050-9004) M820A1 Truck, Van, Expansible (2320-00-050-9007) M820A2 Truck, Van, Expansible (2320-00-050-9010) M821 Truck, Stake, Bridge Transporting (2320-00-050-9015) NHC-250 Cummins 6 Cylinder Diesel Engine M820 Truck, Van, Expansible (2320-00-050-9006)

480 volt 12 lead motor wiring diagram: Electrical Engineer of Australia & New Zealand , 1941

480 volt 12 lead motor wiring diagram: *Wireless World* , 1973

480 volt 12 lead motor wiring diagram: *The Electrical Journal* , 1906

480 volt 12 lead motor wiring diagram: *The Electrical Engineer* , 1911

480 volt 12 lead motor wiring diagram: *IEEE Industrial & Commercial Power Systems Technical Conference* , 1973

480 volt 12 lead motor wiring diagram: *Wireless World and Radio Review* , 1949

480 volt 12 lead motor wiring diagram: *IEEE Conference Record of 1973 Industrial and Commercial Power Systems Technical Conference* , 1973

480 volt 12 lead motor wiring diagram: *Mechanical Engineering* , 1919

480 volt 12 lead motor wiring diagram: *Board of Contract Appeals Decisions* United States. Armed Services Board of Contract Appeals, 2004

480 volt 12 lead motor wiring diagram: *Electrical Review and Western Electrician* , 1911

480 volt 12 lead motor wiring diagram: *The Electrician* , 1906

Related to 480 volt 12 lead motor wiring diagram

Area Code 480 phone numbers - Whitepages Browse area code 480 phone numbers, prefixes and exchanges. The 480 area code serves Phoenix, Gilbert, Tempe, Chandler, Mesa, covering 30 ZIP codes in 2 counties

Area Code 480 - Map, time zone, and phone lookup - CallerCenter About area code 480: location, common spam callers, related area codes, and more. Includes 480 reverse phone lookup to identify spam callers

Arizona Area Code 480 Reverse Phone Number Lookup 1 day ago Free Search of area code 480 and mobile numbers, how to call Arizona, USA, zip codes, local time

480 Area Code - Location, Time, Map, Cities and Census Data 480 Area Code located in Arizona, including 17 cities, 2 counties, 1 time zone, map, Census demographics, and 756 active prefixes

480 area code — information, time zone, map 3 days ago 480 is an area code located in the state of Arizona, US. The largest city it serves is Phoenix. Find out where 480 area code zone from, which states, counties and cities it covers.

480 Area Code - Location, Map, Current Time, Prefixes Area code 480 is located in Arizona.

Get the area's map, cities covered, current time, prefixes, and dialing instructions

Area Code 480: Coverage, Cities, and Key Information Explore area code 480, covering Phoenix's eastern suburbs in Arizona. Understand 10-digit dialing, including mandatory local calls, and the ACC/FCC regulatory landscape

Area codes 602, 480, and 623 - Wikipedia Area codes 602, 480, and 623 are telephone area codes in the North American Numbering Plan (NANP) for most of the Phoenix metropolitan area in the U.S. state of Arizona

480 Area Code - Map, Phone Lookup, Time Zone - Wirefly Find 480 area code details including city, time zone, and map. Lookup area code 480 phone number, name, and location

Amazon's selling a \$480 Eufy robot vacuum for just \$200 (and 10 1 day ago Amazon's selling a \$480 Eufy robot vacuum for just \$200 (and 10 other fab deals) We're also eyeing a celeb-approved anti-aging serum for over 50% off, a cozy fall dress down

Back to Home: <https://old.rga.ca>